



Western Maryland Joint Apprenticeship & Training Committee
Electrical Workers Training Center
307 East Offutt Street
Cumberland, MD 21502



Office Telephone: 301-724-JATC
Ed Crowe, Training Director - Cell: 301-268-9228
wmjadc@atlanticbbn.net



TOOL LIST

INDENTURED APPRENTICE

Knife
Pencil
Six Foot Rule or 16 ft Tape Measure
Channel Locks (2 pairs)
Tool box
Screw drivers- Straight 1/8" Blade
- Straight and Phillips
- Small Phillips and Holding
Pliers- Cutting, Diagonal and Needle Nose
600 Volt Tester
Hacksaw Frame
Crescent Wrench
Hammer
Small Level

UN-INDENTURED APPRENTICE

Six Foot Rule or 16 ft Tape Measure
Screwdriver
Pliers- Cutting
Channel Locks
Knife
Pencil